


29

29

JUNE 1926
ROCK HILL
S. C.



VICTORIA COTTON MILL No. 1
Mutual Risk
DATA FROM MEMS
Admittance Refused

WITHIN THE AREA OF THE MILL ARE LOCATED
SEVERAL HOUSES WHICH WERE BUILT UNDER
AUTOMATIC SPANNERS AND OTHER DATA
IN ORDER TO OBTAIN THE BEST QUALITY
QUALITY OF THE COTTON WARE. THE
SPANNERS, BEING OF THE BEST TYPE,
DO NOT IN ANY WAY AFFECT THE
QUALITY OF THE COTTON WARE. THE
MILL IS A MUTUAL RISK AND THE
MEMBERS ARE NOT TO BE ADMITTED
TO THE MILL.

Scale 100 Ft to One Inch.
Copyright 1926 by the Standard Map Co.